

PART SPEC AUDIT 03-11-15 S22

BROWN-FORMAN

PART .058 X 2.00"

A few important notes during this audit

- **Extreme oscillation at beginning of coil. Set up took over 30 mins due to this. Operators had to crawl up on the table and saw through the steel a few times before getting coil correct.**
 - Per conversation with operator this is not unusual. Coils are loosely banded and come to our plant via rail car**
- **High scrap due to oscillation mentioned above. This coil had a scrap rate of 3.9%. The job as a whole (six coils total) had a scrap rate of 3.66%. The part number is set up in FIT at 3.1%**

Other than those two issues the run was good and had no findings

Part Spec/PO Audit Form

Cust #	1997	Customer	Brown - for main	Grp/Sz/Grd/Width	HRC SS55	058 x 2.00
Equip/Plant	522 / GHD	Work Order #	44702	Date	3/11/15	
Work Order Information		Material to be Used		Actual		
		Tag #1	CA 416154	Tag #2	POW	
Gauge Range	0.050 - 0.100	Gauge Min	0.050	Gauge Min	0.050	
Width Range	1.94 - 2.06	Width	48.5	Width	48.5	
Length Range	N/A	Rockwell	89	Rockwell	89	
Tensile	70-90					
Yield	70-80					
% Elongation	17-30					
Chem Rqmts						
Other Rqmts	no oil/chuck					
	ready to run					
	surfaces CLEAN					
Summary	Holes on coil when run through					
Actions	Pad removed prior to run Coil Oscillated from wall. fixed					
Final Status						

Add to width range 1.75"

1.69" - 1.81"

Oscillation typical loose banding/railcar per Roger

how much weight will that be? typical scrap for this ???

scrap for this coil 3.9%

for full six coil run 3.60%

Had to physically cut through scrap - true suck

Setup over 30 mins, Oscillation issue at least 20 mins

Fit ~~SCAP~~ scrap at 3.10%