

Customer: **All customers**

- Common visual part defects with examples and potential causes.

SCRATCHES, GOUGES, AND DENTS:

- Caused by material handling (forklift or poor stacking and storage).



GAD-VA-009 5.7.20 Rev 1

PITTING:

- Caused at the steel mill by debris on rolls.



LASER SLAG:

- Caused by incorrect laser settings.



ROUGH LASER CUT EDGE:

- Caused by incorrect laser settings.

