Audit Review and Evaluation of Jemison Metals

914 Maero Street NW Trinity, AL 35673

> Dates of Audit: 3/21/17 Date of Submittal: 5/20/17

Auditors: Rick Rowland – SR VP Quality & Engineering

1.0 Summary

This internal audit review provided an evaluation of Jemison Demsey Metals' current level of conformance to ISO 9001, against the current internal audit schedule. The audit measured how effectively the quality management system is implemented in conformance with the applicable requirements and standards (see audit areas underlined in 2.2 below). **Based upon my review**, **the QMS is effectively implemented**.

Audit Detail/Observations/Findings (Detail listed in table at end of report)

4-<u>QMS</u> - Documentation requirements – The following forms and documents were verified during the audit: GAD009 (Receiving form Rev 1 7/11/11), DEC-RC-001 (Receiving Procedure Rev 0 6/23/14), DEC-BB1-CTL (Production Report Rev 2 7/13/16)

<u>6-Resource Mgmt</u> – Employees appeared competent and well trained. Adequate resources (gauges, safety equipment, operating equipment, environment) were observed during the audit.

7.2 – Customer Related Processes

Customer communication/acknowledgement was verified for work order 64196 with Jim Gagnon via phone.

7.5-Production & Service Provision.

Receiving of mill coil 3023837.000 (PO GAD-12408) was observed and tag ND53505 was applied and the coil placed into inventory. PO requirements were verified in Stelplan by receiver.

Work order CLV 64196 (Lincoln Electric) was observed in production (Sales Order CLV 966157). All work order requirements (gauge, width, length, pc count and packaging) were verified as within the work order requirements and recorded onto DEC-BB1-CTL (Rev. 2 7/13/16).

Shipping was audited. Loading orders 3832 & 3833 (CMC Toll) were reviewed. All shipping remarks were followed during the creation of this load (adhesive sleeves for tags, tags to be on same edge as handwriting, tags to be applied before shipment, place plate on truck w/tags facing towards the driver).

7.6-<u>Control of Monitoring and Test Equipment</u>. The following gauges were verified to be calibrated in compliance with calibration records: mic005 in receiving, tape T1010 in receiving, ¹/₂" Jo Block 003, .100" Jo Block 004.

8.3-<u>Control of Nonconforming Product</u> – The sheet non-conforming area was observed. This area is at the north end of the building and is defined by Red Tape on the floor. Demarcation was good; however, there was an area of "old" red tape on the floor against the North wall that could be construed as non-conforming. <u>Observation #1</u>.

Corrective/Preventive Action Follow-Up

CA 11553 – was audited during this audit and documented on the case.

2 other open CAs were reviewed (12450, & 12413), but activities related to these CAs were not occurring.

2.0 Overview

2.1 Personnel Interviewed (Audit evidence found in the Audit

Worksheets)

(officiely	
Greg Chandler (Receiving)	Tim Garth (Lead Operator)
Steven (Operator)	Jim Gagnon (Inside Sales)
Whitney (Operator)	Brent Little (Shipping)
Rachel Howard (QA)	

2.2 Audited Requirements

		7	Product Realization	
4	Quality Management System	7.1	Planning of Product	
4.1	General Requirements		Realization	
4.2.	Documentation Requirements	7.2	Customer-Related Processes	
5	Management Responsibility	7.3	Design and Development	
5.1	Management Commitment		(N/A)	
5.2	Customer Focus	7.4	Purchasing	
5.3	Quality Policy	7.5	Production and Service	
5.4	Planning		Provision	
5.5	Responsibility, Authority and	7.6	Control of Monitoring and	
	Communication		Measuring Devices	
5.6	Management Review	8	Measurement, Analysis and	
6	Resource Management		Improvement	
6.1	Provision of Resources	8.1	General	
6.2	Human Resources	8.2	Monitoring and Measurement	
6.3	Infrastructure	8.3	Control of Nonconforming	
<u>6.4</u>	Work Environment		Product	
		8.4	Analysis of Data	
		8.5	Improvement	

2.3 APPROVAL/SIGN-OFF

Report Prepared by

Rick Rowland

Rick Rowland Lead Auditor/QMR Date 20 May 2017

Nonconforming Corrective Action Report (CAR) for Jemison Metals

CAR	ISO 9000:	Findings/Requirements	Observation	Minor	Major
#	2000 Clause /				
	Sub-Clause				
n/a	8.3 (Control of Non- conforming product)	Observation #1. "Old" red tape on floor at/near non- conforming area could cause confusion regarding the extent of the non-conforming area.	Х		

3/21/17 Internal Audit Decatur 1956/RMB25-613 Production 510 CLV 966157 Steven Lincola Electric Whitney w10 CLV 64196 Actual . 182 nic . 183 nic . 182 Lesur 0.180 - . 196 Gauge HRPO CSBTPCE @ 48.00-48.1875 W. Sth 48.06" 48.06 Verify Jevified Acknowlodgement O DEC-BBI-CTL Sales in fo Q 96 - 96.25 Length 96.125" @ 16 pc. Bundles 7/3/14 Rev. 2 16105 MfL. Moster Gil @ND10192 - Aloil HRPO CSB TP Cot Edge .1790" min x 48" Prochasting JDI / Paperel Wood / no paper Top? 4 Bands Johnathon Bands pc. ct verified Ellison Tags Applied R chaging Shipping Brevit Little cmc - Toll Load pickup=# 3832,3833 Loading orders Pulled material, Taysed, + Pull Stub 3022683.000 D on order 3832. Stub was to order 4 was on B.O.L. 3832 O use Adhesive Sleeves Q Tays to be on Same and as Handariting. O Tags to be appled to shipment O Place plate on Truck Ultass facing towards Drigge Receiving Grey chandler & GA POO9 7/11/11 Per. 1 Reject Area Defined @ PO# GAD 12408 HAPO 46340~ by Red Tape A obs#1 some old Tape against V ND 53505 North wall. Hill Tay 302 3837,000 0.240 min x48 for Conv. to A36 47 4 68.2 TV 31.7 EV For Metal working Solutions & mic 005 Dre 11/19/14 O Type TIOIO 6 1/2 Jo Block 003 0.100 00 004 or 001 Rock Hill, SC 29732 (704) 574-0219 ph. (803) 366-2855 fax \times \times \times \times \times \times \times \times \times \times \times \times \times \times \times \times