**Process/Product Audit Checklist** 

PWC: <u>SCT</u> W/O#: <u>72596</u> Date:				s): 3540026 Auditor: Michael Barnett
Gauge Range: 0.0966 - 0.1/24 Actual Gau	ge: 0. 1	1.020		/idth Range: Width Actual: 60.417
1/9.875 - /20.125 Length Range 95.875 - 96.125 Length Actu		.026	0	ther: Other Actual: 4.17
Other: 50:06 Other Actual: >	.250	<u> </u>	Other	:N/A Other Actual:N/A
Item U	YES	NO	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	X			Terry Wright, Trelvin Grant, Louis Brunson
Correct raw material type and size?	X			Tag(s) to use: 530218  Tag(s) used: 530218
Setup performed according to W/O?	×			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	X			[ <u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	×			Job listed JD4, M. P. Hs medified to Using a JD6.
Visual Inspection performed and product meets requirements?	X			
Out of spec noted, with actions taken?	×			3500045 > 250 out of square. Hetrick Mecias okec to run.
Non-conforming material put into reject warehouse and physically put into non-conforming area?			×	
Required gages available & functional?	X			
All Gages Calibrated (List in Comments)	×			CL2-25'Tape 8-20-18 8-20-19  Gages Observed Mist last calibration and when due)  5'tape 03-03 5-11-18 5-11-19  MS 1"Mb - 8.31.18 - 8.31.19  ST-5 Step gathe gauge - 7-65-18 - 7-05-19  63294 Mass. Table - 4.20.18 - 4.20.19
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	×			
Required PPE being worn?	K			
Forms are the latest revision per Quality Intranet?	X	\$ a. 1994		List Forms (Observed Rev vs Intranet Rev) FoP 081 2-16-01
Hardcopy Controlled Documents are isted on Quality Intranet by location?	X			List Documents and their Location:  SMT - SCT - 001  TM - 01-001