**Process/Product Audit Checklist** 

Cust #: 3503 Customer: 7627			GRP/	Size/GRD/Width: HES 1 10/CS \$ / 13.183
WC.GLI WIDH. 73807 Datel	31.1	13 P	art #(s	1:1630350 Auditor: 6- Smith
Sauge Range: 17/5-1425 Actual Gauge	e: •	130	w	idth Range: 13.713-13.18 Width Actual: 13.17
angth Range: 37.17 -37.11 Length Actua	1: 30	.34	Ot	her: 1.113 - 7.06 2 Other Actual: 2.00
10				∠ Other Actual:  ∠
other: Y Other Actual:	YES	NO	N/A	Comments/Action Taken (Required for NO)
rocess Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> equired?	0			
Correct raw material type and size?	B			Tag(s) to use: 137946  Tag(s) used: 137946
Setup performed according to W/O?	N		4	
Product is acceptable according to customer-specific requirements?  [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	p			[Fab: Print Rev: 1 , W/O Rev: 1 , Part Spec Rev: 1 (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	Ø			WIP P.G. PART
Visual Inspection performed and product meets requirements?	p			
Out of spec noted, with actions taken?			V	
Non-conforming material put into reject warehouse and physically put into non-conforming area?		26771.4	Ø	
Required gages available & functional?	P			
All Gages Calibrated (List in Comments)	Y			Gages Observed (list last calibration and when due) 17032 TAW 17 PUL JAW 18 1212 OCC 17 OUL DEC 17
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?		p		TRACH OVER FLOWING
Required PPE being worn?	p			
Forms are the latest revision per Quality Intranet?	A 1			List Forms (Observed Rev vs Intranet Rev) しんれつのこと REU 1 はら たんし 1
Hardcopy Controlled Documents are listed on Quality Intranet by location?	×			List Documents and their Location:  50 - four  Q.P B.R., MIN OFFICE + PLASM

065: NO MICHONATUR - LOST - BRANCHY 10 OXDER NORE