Process/Product Audit Checklist

10/10/			/Size/GRD/Width: POS 78 HSSO 52.5	_
4-1	19	Part #(s	5):48-00731-S19-Auditor: Z. Deb	
			ridth Range: 97-031 Width Actual: 9.40	records wass. Z3.70
		o Ot	ther: 73-77/2:00 Other Actual: 73.9	recorde
	_		Other Actuals	73.70
YES	NO		Comments/Action Taken (Required for NO)	10.0
/				
			Tag(s) to use: 76809 Tag(s) used: 76809	
/			[Fab: Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)	
	4			
			operator recorded out of spec dimension	
			part was nothing good.	
1			Gages Observed (list last calibration and when due) 17060339 calibration and when due) 0547 spe line 19/16 due 1/20	
/				
	/		List Forms (Observed Rev vs Intranet Rev) 6AD 059 Rev. 0 085 Rev. 0 infraret	
			List Documents and their Location: No controlled locs @ LL	
2	ge: 18	ge: 18 al: 22.0	ge: , 8 W	Width Range: 97-03 Width Actual: 9.00 al: ZZ.00 Other: Z3.77). Other Actual: Z3.9 Other: Other Actual: YES NO N/A Comments/Action Taken (Required for NO) Tag(s) to use: Z6809 Tag(s) used: Z6809 [Fab: Print Rev: O W/O Rev: Part Spec Rev:] (Leave blank if non-Fab audit) Operator recorded out of speck dimension and was actually gend. Gages Observed (list last calibration and when due) 170100339 calipers 7/10 dec 1/20 0547 ape line 11/10 dec 1/20 Use Forms (Observed Rev vs Intranet Rev) (FAD 059 Rev. O 10/20 List Forms (Observed Rev vs Intranet Rev) (FAD 059 Rev. O 10/20 List Documents and their Location:

JDM 501