Process/Product Audit Checklist

				Addit Checklist
Cust #: 3337 Customer: 54101) M	<	GR	P/Size/GRD/Width: POS/13E/ESBTP/boze
PWC: <u> \$\frac{1}{2}\fra</u>	10.23	,F1_	Part #	(s): 47-63707-12 Auditor: B. SWITH
PWC: BSI W/O#: ID5117 Date: 10.23, M Part #(s): 47-63707-12 Auditor: B. SWITH Gauge Range: .043105 Actual Gauge: .548 Width Range: Width Actual: 60.25				
Length Range: <u>120.6250</u> Length Act	ual: <u>170</u>	· 75V	(Other: <u>FUFT 0-170</u> Other Actual: <u>< 178</u>
Other: Sa o- 370 Other Actual:	O., ig		Othe	
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	×			
Correct raw material type and size?	×			Tag(s) to use: 650 59, 650 96 Tag(s) used: 650 59, 650 96
Setup performed according to W/O?	X			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	×			LANGTH AND WIDTH MALL LOON. [Fab: Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?			X	
Visual Inspection performed and product meets requirements?	20			SAMPLAS TAKEN SHOWED COLL BREAKS.
Out of spec noted, with actions taken?				
Non-conforming material put into reject warehouse and physically put into non-conforming area?	X			COILS AND SHEATS REJECTED TO MRB FOR DISPOSITION
Required gages available & functional?	X			
All Gages Calibrated (List in Comments)	\nearrow			0:7 - FLB 19 PUR FLB 120 Gages Observed (list last calibration and when due) T 3033 - AVLIA PUL AVL 120
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	×			
Required PPE being worn?	X			
orms are the latest revision per Quality ntranet?	×			List Forms (Observed Rev vs Intranet Rev) のんと一 BB Iへくれ PEU 4 ソビアモン 4
lardcopy Controlled Documents are sted on Quality Intranet by location?			X	List Documents and their Location:
1		13	78/1	6

JDM 50