CASE 17683

Process/Product Audit Checklist

Cust #: 10 Customer: <u>#F71</u>			GRP	/Size/GRD/Width: <u>//<i>RS/71//IS80/29.6021</i> x <i>_{55.67/./788</i>/v</u>
				s): /37-0480 Auditor: C. ma. A.S.
Gauge Range: <u>./68 ~ ./775</u> Actual Gau	ge: <u>_//</u>	7/	V	/idth Range: /2.61~ /5/76/Width Actual: /2.73
Length Range: Length Actual:			0	ther: 98°- 89° Other Actual: 90.2°
Other: 89° 91° Other Actual: 90	7.50		Other:	V/A Other Actual: NA
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?		V		Now & Paris Total operators to make sure all paper mork is filled out \$2
Correct raw material type and size?			/	Tag(s) to use: 2250/6, 22354/, 222352
Setup performed according to W/O?	V			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	V			[Fab: Print Rev: W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	~			
Visual Inspection performed and product meets requirements?			~	
Out of spec noted, with actions taken?				
Non-conforming material put into reject warehouse and physically put into non-conforming area?				
Required gages available & functional?				
All Gages Calibrated (List in Comments)	/			FO-74-15 JUNA: 19 DUL OLL '19 Gages Observed (list last calibration and when due) 1219 - FAB 19 DUL FAB 20 13077 - 1105947 - TUN'19 DUL TUN'2
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	\ \			
Required PPE being worn?	V			
Forms are the latest revision per Quality Intranet?				List Forms (Observed Rev vs Intranet Rev) 6A0020 RCV VS RCV 6A0059 REV O VS RCV O
Hardcopy Controlled Documents are listed on Quality Intranet by location?				List Documents and their Location: 640-VA-009 Rev-0 5-24-19 Arow office, BreakRown, Plasma Line
01		1	117071	6

JDM 501 opperator said B. wright had

11/8/16 Told opperators to make sure off
Perfor work is filled out correctly
and complete