

**Process/Product Audit Checklist** 

	-55/1	100	WC.	Addit Checking
Cust #: 10 Customer: He;	1		GRF	/Size/GRD/Width: Hes/, 250/ 1650 / /1.34
PWC: <u>fB2</u> W/O#: <u><b>177</b>/10 Date:</u>	4/3	0/19		
Gauge Range: , 275 - , 265 Actual Ga		,		Vidth Range
Length Range: 88.69 - 88.816 Length Act	ual: <b>_88</b>	.75	0	ther: NA Other Actual: NA
Other: Other Actual:	NIA	-	Other	Other Actual:
ltem '	YES	NO	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> requirec?	V			
Correct raw material type and size?		V	L.	Tag(s) to use:  Tag(s) used:  Tag were lost (not on parts in Wil)
Setup performed according to W/O?	/			
Product is acceptable according to customer-specific requirements?  [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	V			[Fab: Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/	33		
Visual Inspection performed and product meets requirements?	V			
Out of spec noted, with actions taken?			/	
Non-conforming material put into reject warehouse and physically put into non-conforming area?		e despe		
Required gages available & functional?	V		-	
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due)  37307302018 - Tape 1211 - Calipa  161,05337 - Leight gage PP00-proton
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?		~		random parts in the floor around the check table
Required PPE being worn?	/			
forms are the latest revision per Quality ntranet?	V			640 020 Rev 1 15 Rev
lardcopy Controlled Documents are isted on Quality Intranet by location?	V			Front office, Plasma, Break born
1 0 1 11 0 1		, 1	1/8/16	

Spoke with operator about not having to a Let him know that it is unexceptable to run a job without a Will tag