**Process/Product Audit Checklist** 

PWC: <u>613</u> W/O#: <u>135 759</u> Date: Gauge Range: <u>235 - 265</u> Actual Ga				#(s): 117-8707-054 Auditor: B. Suctil  Width Range: 8.501-8561 Width Actual: 8.570
Length Range: 594 - 6,06 Length Act				
Other: Other Actual:	NIA			Other records. 1007
Item	YES		Othe	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	X		2	, restain raken (keyan eu lui 140)
Correct raw material type and size?	×		et i	Tag(s) to use: 78009 (
Setup performed according to W/O?	×			730936 TASK A.
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	×		-	[Fab: Print Rev: 4, W/O Rev: 4, Part Spec Rev: 4] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	×			
Visual Inspection performed and product meets requirements?	X			
Out of spec noted, with actions taken?		The Service III COA	×	-
Non-conforming material put into reject warehouse and physically put into non-conforming area?			X	
Required gages available & functional?	X			
All Gages Calibrated (List in Comments)	×			MOID - 11.70.70 por 11.30.21  Gages Observed (list last calibration and when due)  TM 010 - 11.70.70 por 11.30.21  0008 - 7.70.20 Por 7.20.21
lousekeeping: Machine/Floor clean? oose tags & paperwork cleaned up?	×			
equired PPE being worn?	χ			
orms are the latest revision per Quality ntranet?	×		4	List Forms (Observed Rev vs Intranet Rev)  JOW - F - 014 FSV O VS FEV O
lardcopy Controlled Documents are sted on Quality Intranet by location?	×			List Documents and their Location:  6AD-VA-009-ALC FAB WALHINGS, SHIP., \$