## Process/Product Audit Checklist

Cust #: 3393 Customer: Eaton-Ashville			GRP/Size/GRD/Width: POS/.1000/CBTPCE/60		
PWC: SCT W/O#: 93537 Date: 4/10/2024			Part #(	s): 10101AC7TY Auditor: B. Clem	
Gauge Range: .09301070 Actual Gauge: Width Range: 60 - 60.250 Width Actual:					
Length Range: 120 - 120.250 Length Actual:			W-B-F Other: 012 Other Actual:		
SQ Other: 013 Other Actual:			Other: Residual Stress Other Actual:		
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)	
Process Inspection Sheets filled out	1		1.7	Desk audit of process paperwork	
according to <u>frequency</u> and <u>sampling</u> required?		×		Finding: Operator: Marquiez Reid - Inspection document was not saved to the computer. No checks noted on hardcopy of job.	
				Tag(s) to use: NB78746	
Correct raw material type and size?	×			Tag(s) used: NB78746  Coil tag stapled to work order	
Setup performed according to W/O?			х		
Product is acceptable according to customer-specific requirements?  [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]			x	[ <u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)	
Packaging is acceptable according to customer-specific requirements?			х		
Visual Inspection performed and product meets requirements?			х		
Out of spec noted, with actions taken?			х		
Non-conforming material put into reject warehouse and physically put into non-conforming area?			x		
Required gages available & functional?	х				
All Gages Calibrated (List in Comments)	X			Gages Observed (list last calibration and when due) 03-03 25' Tape 3/13/2024 3/13/2025 CL-2 25' Tape 6/18/2023 6/18/2024 M50 1" Mic 1/19/2024 1/19/2025 ST-4 Step Gauge 6/28/2023 6/28/2024 63294 Measuring Table 4/26/2022 4/26/2025	
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?			х		
Required PPE being worn?			Х		
Forms are the latest revision per Quality Intranet?	x			List Forms (Observed Rev vs Intranet Rev) FOP081 2/16/01 1	
Hardcopy Controlled Documents are listed on Quality Intranet by location?	x			List Documents and their Location: SMT-CTL-001 SMT-SH-001 JM-OP-001	

JDM 501 11/8/16 Rev.1

SMT 93537

08Apr24 12:08

JOB WORK ORDER

Jemison Metals - Sumter 1255 North Gate Drive Sumter, SC 29154

Tel: 803-481-0707 Fax: 803-481-0713

Job Type LEV Process Metric Cust N Desc 197780 EATON ASH Due Date 08Apr24 Whs SFG

Setup 00:00 Run 01:35 Prtd By rclar

<<< JOB SPECIFICATIONS >>>

Group POS

Grade CBTPCE Gauge 0.1000 ( 0.0930 to 0.1070) ID

PWC SCT

<>< ORDER SPECIFICATIONS >>> 01 POS/13E/CBTPCE/60.0000"X120.00/.1000N CSB TP CUT EDGE Ord SMT 197780- 1 Cust EATON - ASHVILL Ga 0.1000 Wth 60.0000 Lth 120.0000 3393/10101AC7TY Ga 0.1000 Wth 60.0000 Lth120.0000 Part Ga Rng 0.0930to 0.1070 Pc/Tag WthTol + 0.2500 - 0.0000 Wt/Skd LthTol + 0.2500 - 0.0000 Ty JD1 25 0.0000 Ty JD1 Pk . LthTol + 0.2500 -FLATN: 0.00-.12 WAVE:0.00-.12 BOW: 0.00-.12 SQUA:0.00-.13 \*\*\*\*

do not put paper on top and hang two tags on each skid package on plastic runners must

Do Residual Stress test on this size. 

Check flatness with minimum of 60" piece on flatness table. Determine if there is any EDGE WAVE or CENTER BUCKLE in sheet-segregate

"surface critical, Quality needs to okay any surface imperfections"

Performo Residual Stress test per residual stress procedure \_\_\_\_\_

any nonconforming material and notify supervisor

\_\_\_\_\_\_

Eaton processing instructions for Decatur Check first sheets to get Material in spec Cut 36" to 40" sample every 2 bundles and check on flatness table, flip sample over repeat check. Last bundle must be checked on every order Any material that you cannot see the .250 on the step gage must be put in reject