Process/Product Audit Checklist

PWC: <u>6/4</u> W/O#: <u>//8/252</u> Date:	3/28	120	Part #	s):_50071333 Auditor:_c. 910115.
Gauge Range:	uge:_,	525		Vidth Range: 2.84-2.90 Width Actual: 2.87
Length Range: 7.22 - 7.28 Length Act				
Other: Other Actual:				ther: <u>. 515545</u> Other Actual: <u>. 532</u>
Item	YES		Other N/A	TOTAL TOTAL
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	V			Comments/Action Taken (Required for NO)
Correct raw material type and size?	~	,		Tag(s) to use: <u>238483</u> Tag(s) used: <u>238483</u>
Setup performed according to W/O?	/			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	/			[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?		,		, (Leave Blank in North ab addit)
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?		/		
Non-conforming material put into reject warehouse and physically put into non-conforming area?		✓		
Required gages available & functional?	V			
All Gages Calibrated (List in Comments)	/			Tape Mousine - Thoop MAN 120 OS M
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	V			
Required PPE being worn?		1		
Forms are the latest revision per Quality ntranet?	/	,	L	st Forms (Observed Rev vs Intranet Rev) GAD 20 Rev I vs Rev I
Hardcopy Controlled Documents are isted on Quality Intranet by location?	/		Li 6	st Documents and their Location: ヘローリケーロウィーとASUS、PESS BRAKES、SITIV