

## Process/Product Audit Checklist

Cust #: <u>3337</u> Customer: <u>Eaton-MX</u> GRP/Size/GRD/Width: <u>POS/14F/CSOTP/60.25</u>			
PWC: <u>BBI</u> W/O#: <u>96350</u> Date: <u>6/10/19</u> Part #(s): <u>47-63707-13</u> Auditor: <u>JP</u>			
Gauge Range: <u>080-.096</u> Actual Gauge: <u>.085</u> Width Range: <u>62.25-62.75</u> Width Actual: <u>60.75</u>			
Length Range: <u>120.625-120.875</u> Length Actual: <u>120.75</u> Other: <u>5-.37 Max</u> Other Actual: <u>5-.062</u>			
Other: <u>N/A</u> Other Actual: <u>N/A</u> Other: <u>N/A</u> Other Actual: <u>N/A</u>			
Item	YES	NO	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	✓		
Correct raw material type and size?	✓		Tag(s) to use: <u>896011</u> Tag(s) used: <u>896011</u>
Setup performed according to W/O?	✓		
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	✓		[Fab: Print Rev: _____, W/O Rev: _____, Part: Spec Rev: _____] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	✓		
Visual Inspection performed and product meets requirements?	✓		
Out of spec noted, with actions taken?	✓		<u>1 sheet removed/out of figure</u>
Non-conforming material put into reject warehouse and physically put into non-conforming area?		✓	<u>Scrapped 1 sheet</u>
Required gages available & functional?	✓		
All Gages Calibrated (List in Comments)	✓		Gages Observed (list last calibration and when due) <u>Tape - 71031 71026 - AUG 18 Due AUG 19</u> <u>Micrometer - 012 FKR 19 Due FKR 20</u>
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	✓		
Required PPE being worn?	✓		
Forms are the latest revision per Quality Intranet?	✓		List Forms (Observed Rev vs Intranet Rev) <u>DEC-BBI-LTL 4/20/17 Rev 4 vs Rev 4</u> <u>DEC-PKG-001 11/25/18 Rev 5 vs Rev 5</u>
Hardcopy Controlled Documents are listed on Quality Intranet by location?	✓		List Documents and their Location: <u>QP - Bulkhead Board</u> <u>JO Shid - Pkg + wood areas</u>