Process/Product Audit Checklist

PWC: <u>SRB</u> W/O#: <u>66.093</u> Date: <u>6</u> O300 0330 Actual Gauge Range:		<u>- 1:/</u>	Part #(s	2.212_10.023	
37 210 - 27 202				ATT	
	al: 37	.a6	01 عا	ther: <u>2824 lbs.</u> Other Actual: <u>2824 lbs.</u>	
Other: O-12 Other Actual: .	007		Other:		
Item	YES	NO	N/A		
Process Inspection Sheets filled out				No Flatness Check noted on	
according to <u>frequency</u> and <u>sampling</u> required?	:	~		San J. Details on Back	
icquico:				Tag(s) to use: 511174	
Correct raw material type and size?	V			Tag(s) used: 511174	
Setup performed according to W/O?					
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]				[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)	
Packaging is acceptable according to customer-specific requirements?					
Visual Inspection performed and product meets requirements?					
Out of spec noted, with actions taken?					
Non-conforming material put into reject warehouse and physically put into non-conforming area?				· ·	
Required gages available & functional?	~				
All Gages Calibrated (List in Comments)	~			Gages Observed (list last calibration and when due) 8-3 25' Tape 5-25-17 5-25-18 m-44 1" mic 6-28-16 6-28-17 ST-5 Step Gauge 7-5-16 7-5-17 63294 megs, Table 4-19-17 4-19-18	
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	~				
Required PPE being worn?		~		Sam J No Safety Blasses -	Det
Forms are the latest revision per Quality Intranet?	/	•		List Forms (Observed Rev vs Intranet Rev) SmT-SRB-001 11-8-16 5 Jm-08-001 4-31-15 0 F08081 2-16-01 1	
Hardcopy Controlled Documents are				List Documents and their Location:	

Sam J - Wearing safety Glasses on top of head.

No Flatness check noted on Foposi for 26.920 x 21.9050 or 18.8500 x 37.2500