**Process/Product Audit Checklist** 

		#(s): CUS 579 Auditor: P. Smith
		Width Range: 36.52-36.64Width Actual: 36.55
		Other: <u>1644</u> Other Actual: , 40
Other:Other Actual: Item	<i>~/4</i>   YES	er: <u>~     A   A   A   A   A   A   A   A   A </u>
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	×	The Print AND MIC VERIFICATION GADOZO
Correct raw material type and size?	0	Tag(s) to use: 196519 + 198717  Tag(s) used: 196519 193712
Setup performed according to W/O?	X	
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	×	[ <u>Fab:</u> Print Rev: A, W/O Rev: A, Part Spec Rev: A (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	X	
Visual Inspection performed and product meets requirements?	×	NO SCRATTURE @ BAGINAINO
Out of spec noted, with actions taken?	X	6 SCRACE END OF BUNDLE
Non-conforming material put into reject warehouse and physically put into non-conforming area?	X	
Required gages available & functional?	×	
All Gages Calibrated (List in Comments)	×	TRUSS-JAW 19 DUL JAW 20 Gages Observed (list last calibration and when due) 1204 - AV6 18 DUL AU6 19 093 - AU618 DUL AU617
dousekeeping: Machine/Floor clean?  oose tags & paperwork cleaned up?	×	
Required PPE being worn?	K	
Forms are the latest revision per Quality ntranet?	X	List Forms (Observed Rev vs Intranet Rev)  6 1020 RAN   VS RAN
Hardcopy Controlled Documents are isted on Quality Intranet by location?		List Documents and their Location: