John Foster

Talked to sperator about Keeping his workstation clean

Process/Product Audit Checklist

Cust #: 10 Customer: HEI	L		_ GRP	/Size/GRD/Width: HLS 9E H580	
PWC: <u>666</u> W/O#: <u>10307</u> 9 Date:	7-24	-19	Part #(s): 113 -6654-008 Auditor: John Fortes	
Gauge Range: 182 - 162 Actual Gau	Name and Address of the Owner, where			/idth Range: <u>৫০,০5-১৯.୮</u> TWidth Actual: <u>১০,</u> /০	
Length Range: //১/// -/১/5/ Length Actu	a :/	56,5	O	ther: N7 Other Actual: NA	
Other: Other Actual:	NI		Other:	Other Actual:	
Item	YES	NO	N/A	Comments/Action Taken (Requirec for NO)	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	1			S.	
Correct raw material type and size?	V			Tag(s) to use: 2.11366 + 211367 Tag(s) used:	
Setup performed according to W/3?	/				
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	2			[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit,	
Packaging is acceptable according to customer-specific requirements?	/				
Visual Inspection performed and product meets requirements?	V				
Out of spec noted, with actions taken?			V	25 (2	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			V		
Required gages available & functional?	X)			
All Gages Calibrated (List in Commerts)	X			Gages Observed (list last calibration and when due) No tape at 6L6 - coon found THR MIC - 2087 Calipar - 12/8 -007	19.0%
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?		V		Work station disorganized wish payers & pourts, alones	
Required PPE being worn?	X				
Forms are the latest revision per Quality Intranet?	X			CADOZO LEV 1 US PEN 1	
Hardcopy Controlled Documents are listed on Quality Intranet by location?	4			List Documents and their Location: CAD VA 29 Rev 6 - VISUAL ATO	