

Process/Product Audit Checklist

Gauge Range: .045-,051 Actual Ga	uge:	048	,	Nidth Range: 48-48.35 Width Actual: 49.063
Length Range: 216-716-17 Tength Act	_	_		Other: VA Other Actual: VA
Other: N/A Other Actual:	1		Other	
item	YES	I NO		
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	V			O. H. O.
Correct raw material type and size?	V			Tag(s) to use:
Setup performed according to W/O?	V			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	V			[Fab: Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	V			
Visual Inspection performed and product meets requirements?	~			
Out of spec noted, with actions taken?			V	90 SO (
Non-conforming material put into reject warehouse and physically put into non- conforming area?			V	
Required gages available & functional?	V			
All Gages Calibrated (List in Comments)	V			Gages Observed (list last calibration and when due) Tape 010 7-17 Thrw 1-18 M:c. 043 7-17 Thrw 1-18
Housekeeping: Machine/Floor clean? Hoose tags & paperwork cleaned up?	N			
lequired PPE being worn?	V			
orms are the latest revision per Quality ntranet?	V			List Forms (Observed Rev vs Intranet Rev)
lardcopy Controlled Documents are isted on Quality Intranet by location?		ļ 		List Documents and their Location: Lyw -F-DOI - Server