Audit Review and Evaluation of Jemison Metals

3001 Hickory Street Gadsden, AL 35902

Dates of Audit: 8/15/18 Date of Submittal: 8/17/18

Auditors: Rick Rowland – SR VP Quality & Engineering

1.0 Summary

This internal audit review provided an evaluation of Jemison's current level of conformance to the ISO 9001:2015, against the current internal audit schedule. The audit measured how effectively the quality management system is implemented in conformance with the applicable requirements and standards. **Based upon our review, the QMS is effectively implemented.**

Audit Detail/Observations/Findings

7.5 – Documented Information

The following forms and documents were verified during the audit: DEC-BB1-CTL 6/26/17 Rev.4 at GCT, JDM200 Quality Policy Hardcopy Posting (Entry, Breakroom, Plasma), GAD009 (rcvg) Rev.1, GAD014 Rev2 (QA),

JDM-F-008 8/12/16 Rev. 1 **OBS** 1: This form has JDF-F-008 in the footer rather than JDM-F-008. Needs to be corrected.

7 Support

Employees appeared competent and well trained. Adequate resources (gauges, safety equipment, operating equipment, environment) were observed during the audit.

7.2 Competence

Reviewed Cody Mathis (Plasma Operator) training documentation. New Hire training documented on 2/5/18 (Rev 7 and turned into human resources. (Current Revision 8, Already noted in CLV audit as CLV Minor #1)

8.2 Requirements for products and services

Heil PO# 24184961 received 8/13 with 8/16/18 due date. Acknowledged by Betty Crosley on 8/13/18 via email. This is the material that was observed on work order 81116 at the plasma. Sales Order 76989 entered for the order.

8.4 Control of Externally provided processes, products and services PO gad-14213 was reviewed and compared against GE Lighting TX's requirements. Gauge, Grade, Width requirements met the part spec requirements. See attached audit notes for detail. John Cordell in Receiving. OFI #1: No documented receiving procedure. One hasn't been needed as John has been receiving for decades. However, if John retires or leaves Jemison we should take the benefit of his experience and document it into a procedure.

8.5-Production & Service Provisions

Mill coil 3438041.002 received against PO GAD 14213 on receiver 43691 for GE Lighting. PO requirements verified on GAD009 and are available in the attached audit notes.

Production: W/O GAD-81116, Heil Fab, Sales Order 76989 was observed at the plasma. Cody Mathis was the operator. First piece inspection performed and documented on Jemison Print W137-0601-025 Rev 0 / C. All checks were within the range identified on the Jemison Print. Minor: 1: Operator did not have the tag for the material to be used available. All material must be clearly identified. Risk in this event was low due to gauge, width and length checks as well as the fact that this is a very specific size and is likely not to cause a mix issue. However, we should take CA to prevent recurrence.

W/O GAD-81725, GE Lighting TX, was observed at GCT. Chris Ellis was the operator. All work order requirements were documented on DEC-BB1-CTL and met part spec requirements (see attached audit notes). Packaging met the work order requirements as well (paper wrapped, Heat Treated Skids, Ring Shank nails, 3x4 length runners turned sideways for line clearance, skids to have crossblocks on bottom, 2,500 lb max weight, JD6).

Preventive Maintenance:

Reviewed PMs with Wayne Angle. PM schedule for each piece of equipment is done weekly. Maintenance helper is performing the bulk of the PM's with operators assisting on some equipment. GCT maintenance records were reviewed and were up to date. Forklift daily and crane daily (Bay 1, #1) inspection records were reviewed and found to be in good order.the line is organized by weeks. Crane in Bay 1, #1 annual safety inspection reviewed. 1 code violation was reported, hydraulic braking. Jemison Maintenance has since installed variable frequency drives on all cranes.

7.1.5 Monitoring and Measuring Resources

The following gauges were verified to be calibrated in compliance with calibration records: Receiving: 2088 0-1" Mic, 25' Tape 3039, Scale 321909, Plasma: 25' Tape T3051, 0-1" Mic 2086, 12" Caliper 1205, GCT 0-1" Mic 2071, 16' Tape T3052

8.7 Control of Nonconforming Product

Reject Area for finished goods clearly segregated and only 2 bundles (Tags 179000 & 178990 labeled for Edgewave and in mill claim) and 4 coils (BW96445R for pickle stain in mill claim).

10.2 Nonconformity and Corrective Action

Quarterly QA call minutes reviewed. Call was on 8/10/18. Attendees listed. Metrics, CA's, customer visits etc reviewed.

10. Improvement

Implementation of Dayforce, cloud based payroll, time and attendance system, initial training complete, full roll out and training to be implemented by end of first quarter 2019.

Development of a camera system for viewing surface (top or bottom) is in process. BHM has the prototype, GCT is in progress. This is part of the BEST project/machine intelligence.

Key Metrics: Internal and External DPPM + OTD were posted on Quality Board.

Observations and findings from previous ISO audit

Observations:

- 1 Complete 6/8/17
- 2 Complete 6/8/17
- 3 Complete 2/7/18
- 4 Complete 2/16/18
- 5 Complete 6/7/17
- 6 Complete 6/7/17
- 7 Complete 6/7/17
- 8 Complete 1/1/18
- 9 Open. Hit miss on daily. Plan is for weekly 5S audits by John, Bradley & Brian.

Corrective/Preventive Action Follow-Up

CA 14798 Still Open awaiting overarm tooling before closing. No other open CA's.

2.0 Overview

2.1 Personnel Interviewed (Audit evidence found in the Audit

Worksheets)

John Cordell (Receiving)			Wayne Angle (Maintenance)				
Chris Ellis (Rowe Operator)			Betty Crosley (Inside Sales)				
Cody Mathis (Plasma Operator)			Brian Smith (QA)				
2.2	Audited Requirements						
		-					
	4	Context of the Organization	8 Operation				
	4.4	Quality Management System	8.1 Operational planning and				

and its processes 5 Leadership

- 5.1 Leadership and commitment
- 5.1.2 Customer Focus
- 5.2 Policy
- Management review 5.6
- Planning 6
- 7 **Support**
- 7.1.1 General
- Competence 7.2
- 7.1.3 Infrastructure
- 7.1.4 Environment for the operation of processes
- 7.1.5 Monitoring and measuring resources
- 7.5 Documented information

- control
- 8.2 Requirements for products and services
- 8.3 Design and development of products and services (N/A)
- 8.4 Control of externally provided processes, products and services
- 8.5 Production and service provision
- 8.7 Control of nonconforming outputs

Performance evaluation

- 9.1 Monitoring, measurement, analysis and evaluation
- 9.1.1 General
- 9.1.3 Analysis and evaluation

10 **Improvement**

10.2 Nonconformity and corrective

action

2.3 APPROVAL/SIGN-OFF

Report Prepared by Rick Rowland

Rick Rowland Lead Auditor Date 17 August 2018

Nonconforming Corrective Action Report (CAR) for Jemison Metals

CAR	ISO 9000:	Findings/Requirements	Observati	Mino	Major
#	2015 Clause /		on	r	
	Sub-Clause				
OBS	7.5	JDM-F-008 has JD"F"-F-008 in footer. Typo needs to	X		
1		be corrected.			
Minor 1	8.5	Operator did not have the tag for the material to be used available. All material must be clearly identified. Risk in this event was low due to gauge, width and length checks as well as the fact that this is a very specific size and is likely not to cause a mix issue. However, we should take CA to prevent recurrence.		X	
OFI 1	8.4	No documented receiving procedure. One hasn't been needed as John has been receiving for decades. However, if John retires or leaves Jemison we should take the benefit of his experience and document it into a procedure.	X		

Revg John Bordell & GADOOQ 7/11/11 Rev. 1

PO GAD 14213 Revr 43691 PA1008 CSB

O Gauge . D266 Ain Mill Coil 3438041,002

Master Tay .0786 Act GE Lighting

BND 59433 O Coil 18-24k 23.4k Actual

O-1" MIC 2088 Revg 418 due 1/2

Tape 3039 25 Revg May 18 due May 19

Scale 32/909 Capacity? 70K 6/22/18

6-22-18 May

Dec 2056 May

O Tape 3039 25 Revg May 8 due May 19

510 76989 due 8/16/18 Heil Post 24/8496 |

Plesma Cody Mathis

W/O 8/11/6 Heil-Fab

W/37-0601-025 Jen Cort Re

Print 137-0601-025 Rev. Or 0/0

Gavse Program 6742 pa Phay

B-W. oth Desired 180302

C-Hole Suly 60 #180, but no tex

9/12 Caliper 1205 PL, Feb 18 due 1/9

0 40 0020 9/3/15 Rev. |

O GAD 0020 9/3/15 Rev. |

GCT - Chris Ellis

GAD 81725 GE Lighting TX

CRS 22 CS8 48 x 98

Ø .0269-.0329 Gause rotal

Ø 48-48.1875 W: 1th 48 18

Ø 98-98.25 Lougth 98 3/14

Ø Wave/BOW .18 MOX .18

Ø Square .25 may .18

Material ND 59388

Packasins

Offsper wrap

OH.T. Skids

ORing Shank Mails

ORING Shank M

DEC-BBI-CTL Rev. 4

DO-1"Mic 2071 artisticate

Tape 16" T3052

4 Rowe 8/18 due 8/9

Leways

A Bottom

QA Ø GADO14 11/30/15 Rw. 2

Rev-us Process

OFAD-FAB-002 Rev-up Procedure

OFFORM has JDF-F-008

OFFORM has JDF-F-00

verified.

Non conforming Area
Tay 179000
178990
Both tagged for
Edge wave on
Mill Claim

BW96445 R Pickle Stafn on Colle Mill Claim Novi7 & poor Protractor P.A.

DPOOR Digital Protractor
Novi8

T 3048 Tepe 16 years

D12" Caliper 1207 P.B. war 18 due Mar 19

PM. Woyne Angle

Forklifts
Daily by
Maint, Helper
on File
Sow 7/23-8/13

Cranes
Daily - assigned personnel
Bay 1 #1 Crane
Up Chris Ellis.

14 Chris Ellis.
Sow July. Check August @ Line
@ Roweline thru 8/15/18

Verified GCT

weakly checklist

performed by Maint.

Helper.

Every 12 mps. FHS, Florida Handling
Every 12 mps. FHS, Florida Handling
Systems
Crume#1 Code Violation reported 1204 Winthrop Dr.
For Bridge Brake. Rock Hill. SC 29732
We Changed to variable
Speed Drive in Q1 2018

O Jomzoo Hardroly Breakroom, Entry O Metrics Posted on Bourd Overall Cleanliness - Good

LOHR

(704) 574-0219 ph. (803) 366-2855 fax

COMPANY...CAROLINAS