**Process/Product Audit Checklist** 

Cust #: 3436 Customer: TWESTER			GRP/Size/GRD/Width: HRS/10 HSSO /28.71× 9 6		
PWC:644 W/O#: 13488 Date	: 7.19.	21		(s): 720 2532 Auditor: 8. 8mg 71	
Gauge Range: 1265 142 F Actual Ga	uge:	.133		Width Range: <u>28.17 - 73.25</u> Width Actual: <u>78</u> . 71	
Length Range: 2.96.94 Length Ac	tual:	76.01		Other: Other Actual:	
Other: Other Actual:	NH		Othe		
Item	YES			777	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	×				
Correct raw material type and size?	<b>A</b>			Tag(s) to use: 276679  Tag(s) used: 276679	
Setup performed according to W/O?	×				
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	p			[Fab: Print Rev: _ C _ , W/O Rev: _ C _ Part Spec Rev: _ C _ ] (Leave blank if non-Fab audit)	
Packaging is acceptable according to customer-specific requirements?	ø			, and addity	
Visual Inspection performed and product meets requirements?	X				
Out of spec noted, with actions taken?			4		
Non-conforming material put into reject warehouse and physically put into non-conforming area?			p		
Required gages available & functional?	×				
all Gages Calibrated (List in Comments)	×			Gages Observed (list last calibration and when due (007 7.20.20 OUL 7.21.21 TMO9-11.30.20 OUL 11.30.21 MOO9 -11.30.20 OUL 11.30.21	
lousekeeping: Machine/Floor clean? oose tags & paperwork cleaned up?	X				
equired PPE being worn?	Ø				
orms are the latest revision per Quality atranet?	K			Jon -f-014 fru ous fruo	
ardcopy Controlled Documents are sted on Quality Intranet by location?			Q	List Documents and their Location:	

GAD-VA -ON PRO US RUD