Process/Product Audit Checklist

Gauge Range: 17/3/1873 Actual Gaug	e: //	715	w	idth Range: 20 18 (25.3) Width Actual: 26.19
ength Range: 25.25/25.37 Length Actua				her: Other Actual: 1/A
Other: N14 Other Actual:	N	14-	Other:	
tem	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to frequency and sampling required?	/			
Correct raw material type and size?	1		21	Tag(s) to use:
Setup performed according to W/O?	V			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	/			[Fab: Print Rev: L. W/O Rev: L. Part Spec Rev: L. (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/			
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?	1			
Non-conforming material put into reject warehouse and physically put into non-conforming area?	1		V	
Required gages available & functional?	V			
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due) 1207 No. 18 duc with Fi 1207 No. 18 duc out 19 16051038 NN 17 due No. 18
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	/			
Required PPE being worn?	1		n ag	
Forms are the latest revision per Quality Intranet?	V			List Forms (Observed Rev vs Intranet Rev)
Hardcopy Controlled Documents are listed on Quality Intranet by location?	V			List Documents and their Location: front office & Break Room, and Plastad line