Process/Product Audit Checklist

Gauge Range: - 093 - 103 Actual Gaug	e: ,	096	W	lidth Range: 64.25- ME Width Actual: 61.00
Length Range: 120-625 - 121. 9/3 Length Actus	al: /2	0.75	0	ther: 5 37 Max Other Actual: 5 - , 187
Other: MA Other Actual:	11	7	Other:	MY Other Actual: M/
ltem 1	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	1		H	
Correct raw material type and size?	/			Tag(s) to use:
Setup performed according to W/O?	/			
Product is acceptable according to customer-specific requirements? [Fab: is the Part Print Present & the correct Revision? Are required measurements documented?]	V	1		[Fab: Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/			
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?			/	All material was conferring
Non-conforming material put into reject warehouse and physically put into non- conforming area?			/	↓
Required gages available & functional?	1		7	
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due) To 31 - Tape - HUL 118 Out 1001 19 Moo8 - Micrometer - Duy 118 Ax July 119
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	1			
Required PPE being worn?	V			
Forms are the latest revision per Quality Intranet?	/			tist Forms (Observed Rev vs Intranet Rev) OEC-BBI-CTL 6/20/17 REV 4 VS P OEC-Pts-001 10/25/18 Rev 5 V5 F
Hardcopy Controlled Documents are listed on Quality Intranet by location?	X		11/8/	Ust Documents and their Location: Q.P Dulleth Locat JO Shid - Pks + wood Areas