## **Process/Product Audit Checklist**

Cust #: 333 7 Customer: 64T -	шx	<del></del>	GRF	/Size/GRD/Width: POS / 13 E / CSVTP / 48.00	
PWC: <u>881</u> W/O#: <u>179643</u> Date:	12.16.	20_	Part #(	s): <u>47-63907-124</u> Auditor: <u>B.S.m.171</u>	
Gauge Range: <u>・グパー、ハケー</u> Actual Gau	ge:	.095	v	Vidth Range: 48.99 - 48.05 Width Actual: 48.12	
Length Range: 170 ይህና - 1200 Length Actu	ıal: <u> </u> /2	0.75	o	ther: <u>SQ 0.034</u> Other Actual: <u>062</u>	
Other: <u>Bow D.o - 12*</u> Other Actual: <u>Z</u>	.:125 YES	NO	_Other	:Other Actual:	
Process Inspection Sheets filled out	( TES	NO	I N/A	Comments/Action Taken (Required for NO)	
according to <u>frequency</u> and <u>sampling</u> required?	D				
Correct raw material type and size?	Ø	40		Tag(s) to use: <u>ND 68897</u> Tag(s) used: <u>ND 68897</u>	
Setup performed according to W/O?	X				
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	×			[ <u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)	
Packaging is acceptable according to customer-specific requirements?	×				
Visual Inspection performed and product meets requirements?	Х			FOUND PITS ON BOTTOM SIDE - OK NOTIFIED STEES + CUSTOMAR.	F \$
Out of spec noted, with actions taken?			入		
Non-conforming material put into reject warehouse and physically put into non-conforming area?			70	V 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
Required gages available & functional?	B				
All Gages Calibrated (List in Comments)	۸			G3372 - TMBLL FRB'ZO DUL FKB'ZI Gages Observed (list last calibration and when due) 013 uml - FRB'ZO DUL FLB'ZI TIOIS TMR - DLL'ZO DUL PEL'ZI	
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	¥				
Required PPE being worn?	\$				
Forms are the latest revision per Quality Intranet?	æ			List Forms (Observed Rev vs Intranet Rev)  DAC-PK6-001 FW 5 VS PW 5  DEC-BSI-CTL REN 4 VS RAN4	
Hardcopy Controlled Documents are listed on Quality Intranet by location?			ኦ	List Documents and their Location:	

JDM 501