Process/Product Audit Checklist

Gauge Range: , 693 /03 Actual Gaug	e o	93	W	ridth Range: 60.25-ME Width Actual: 61.00
Length Range: /24.675-124-613 Length Actus				ther: \$ 87 Max Other Actual: \$ /25
Other: MT Other Actual:	MA		Other:	N/1 Other Actual: N/4
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	/			
Correct raw material type and size?	/		4.5	Tag(s) used: <u>NO 40575</u>
Setup performed according to W/O?	/	100 300		
Product is acceptable according to customer-specific requirements? (Fab: is the Part Print Present & the correct Revision? Are required measurements documented?)	/	18		<u>[Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/			
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?			1	
Non-conforming material put into reject warehouse and physically put into non- conforming area?			/	
Required gages available & functional?	/			
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due) TO 31 - Tape - 906 18 0 04 106 19 Moo 8 - Micros & - 5064 18 202 5064 19
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	/			
Required PPE being worn?	/		DILL	
Forms are the latest revision per Quality Intranet?	/			DEC-DD1-C7L 6/20/17 Ray 45 F DEC-P66-001 10/25/13 Ray 5 VS
Hardcopy Controlled Documents are listed on Quality Intranet by location?	/		11/8/1	List Documents and their Location: at - Bwitch hard 50 Shid- 1ks + wood area

JDM.