Jul

Process/Product Audit Checklist

Gauge Range: 067-074 Actual Gau	ge: • 0	72	v	/idth Range: <u>6425-ME</u> Width Actual: <u>6</u> 0. 50
Length Range: Length Actu				ther: 5 37 Ask Other Actual: 5 250
Other: N/A Other Actual:	al d			w/A Other Actual: w/A
Item	YES	NO	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	/			
Correct raw material type and size?	/			Tag(s) to use: <u>62 ¥ 3 3</u> Tag(s) used: <u>62 ¥ 3 3</u>
Setup performed according to W/O?	1			
Product is acceptable according to customer-specific requirements? (Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?)	/			[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?				
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?			/	
Non-conforming material put into reject warehouse and physically put into non- conforming area?			/	
Required gages available & functional?				
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due) Tape - 70031, 7026 - 47618 PVE AVE' Aicromater - 012 F46'19 OVE f46'20
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?				
Required PPE being worn?	~			7
Forms are the latest revision per Quality Intranet?	1			List Forms (Observed Rev vs Intranet Rev) BEC-BDI-CTL Web/17 Res 4 5 10 OEC-PKG-001 10/25/18-Rev 5 15
Hardcopy Controlled Documents are listed on Quality Intranet by location?				List Documents and their Location: Of - Bulletin Abard Joshid - Plat + wood areas