Derl

**Process/Product Audit Checklist** 

Gauge Range: <u>めうろー, /じらひ</u> Actual Ga				(s): <u>47 -63107-12</u> Auditor: <u>605</u> Width Range: <u>61.2495-0</u> 2 Width Actual: <u>60.875</u> "
Length Range: 10.5075-120.62				Other: <u>SQUARE - 37</u> Other Actual: <u>.062</u> 250"
Other:Other Actual:	M		Othe	who
Item	YES	NO	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	X			•
				Tag(s) to use: NO 610778
Correct raw material type and size?	×			Tag(s) used: NO 61978
Setup performed according to W/O?	X			SMARH -OX
Product is acceptable according to customer-specific requirements?  [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	×			[ <u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	Q			
Visual Inspection performed and product meets requirements?	p			
Out of spec noted, with actions taken?			×	
Non-conforming material put into reject warehouse and physically put into non- conforming area?			<b>%</b>	
Required gages available & functional?	×			
All Gages Calibrated (List in Comments)	×			012 - 126:19 04 (46:120) Gages Observed (list last calibration and when due) \$124316 - 5014 118 004 5014 119 004 - 7.27.18 004 7.27.19 002 - 7.27.18 004 7.27.19
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	0			
Required PPE being worn?	~			
orms are the latest revision per Quality ntranet?	, ,			List Forms (Observed Rev vs Intranet Rev) PRL-BBI-(TL- ないりょう ないり PRL-PKB-061- ないては、アンケ
lardcopy Controlled Documents are sted on Quality Intranet by location?	×			List Documents and their Location: Q、アードルに行い じのいめ