Process/Product Audit Checklist

Cust #: 10 Customer: +42	11		GRP	/Size/GRD/Width: HLS/96/HS81/ 2467	
PWC: (132 W/O#: 14014 Date:	515	17	Part #(s): 737-9604-014 Auditor: 6 front	
Gauge Range: . 152 167 Actual Gau	ge:	155	W	Vidth Range: 29, 331-24.60 Width Actual: 24.69	
Length Range: <u>717. g 3ረ -247</u> ምይngth Actu	al: <u>74</u>	175	0	ther: 33° - 35° Other Actual: 34°	
Other: 55-57 Other Actual:	570			: 10,21-10.41 Other Actual: 10.3C	
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	Ø				
Correct raw material type and size?	Q			Tag(s) to use: 147491 147472 147473 14997 Tag(s) used: 147471 ,147472 147475	
Setup performed according to W/O?	Ø				
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	A			Typo 10 SPAC - SHOULD REV C (ORAWING SIZE) CHANGED TO (-). [Fab: Print Rev: (-), W/O Rev: (-), Part Spec Rev: C] (Leave blank if non-Fab audit)	237-9604-01 237-9604-01
Packaging is acceptable according to customer-specific requirements?	P				
Visual Inspection performed and product meets requirements?	A				
Out of spec noted, with actions taken?			Ø		
Non-conforming material put into reject warehouse and physically put into non-conforming area?			7		
Required gages available & functional?	Ø				
All Gages Calibrated (List in Comments)				Gages Observed (list last calibration and when due) #1210 mach 17 Pul mach 18 #0Paul 9.29.16 Dul 9.29.17	
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	D				
Required PPE being worn?	X				
Forms are the latest revision per Quality Intranet?	Ø			List Forms (Observed Rev vs Intranet Rev) 6000 Pau (US Puu) 60009 Pau O US Puu O	
Hardcopy Controlled Documents are listed on Quality Intranet by location?	Ø	111	11/8/1	List Documents and their Location: GADOLO PLAGNA GADOLG FURWING	Rev.1