## **Process/Product Audit Checklist**

				P/Size/GRD/Width: HNS/5545   12F /4.41 / 8.81
				(s): 113-332800 Auditor: 6.50000
Gauge Range: ./bg //9 Actual Gau	ge: <u>.</u>	111	\	Vidth Range: <u><b>9.788 - 8.97</b></u> Width Actual: <u><b>8.8</b> 7</u>
Length Range: 4.648 - 4.37 Length Actu	ıal: <b>C</b>	1.70	C	ther: <u>9° - 71°</u> Other Actual: 71°
Other: . 71 84 Other Actual:	.81		Other	:Other Actual:
ltem	YES	NO	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	×			
Correct raw material type and size?	×			Tag(s) to use: <u>78/088, 28/084</u> Tag(s) used: <u>28/088</u> , <u>28/084</u>
Setup performed according to W/O?	x			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]		p		SPEC / W/O PAU INCORRECT.  STOCKS CORRECTED ON 5.28.2  [Fab: Print Rev:, W/O Rev: _A, Part Spec  Rev: _A] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	P			PALLET
Visual Inspection performed and product meets requirements?	×			
Out of spec noted, with actions taken?			X	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			×	
Required gages available & functional?	R			
All Gages Calibrated (List in Comments)	K			1610587 - 6.9.20 PUC 6.18.21 Gages Observed (list last calibration and when due) PD - 94-15 - 1.18.21 PUC 7.18.21 POC 7.18.21 POC 7.20.20
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	×			
Required PPE being worn?	×			
Forms are the latest revision per Quality Intranet?	χ			List Forms (Observed Rev vs Intranet Rev)  TDM - F - O15
Hardcopy Controlled Documents are listed on Quality Intranet by location?	A			List Documents and their Location: したローットーのリーシャル3 しへローットーのターシャル3