## **Process/Product Audit Checklist**

PWC: <u>LP1</u> w/0#: <u>35688</u> Date: <u>5</u>	5/29/2	4	Part #(s	S):WF559482CGU_Auditor:N. TZAGLAND
Gauge Range: <u>೦,೦૫,-೦,೦ಽ೦</u> Actual Gau	ge: <u>0.67</u>	27	W	fidth Range: 48.957 ± 6 의 Width Actual: 48.946
Length Range: 5억.5여 호마스 Length Actu	al: <u>ऽ</u> %	500	01	ther: 45.81( ± .010 Other Actual: 45.81
Other: N/A Other Actual: N/A	4		Other:	N/A Other Actual: N/A
ltem	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	<b>\</b>	7		OPERATORS - T.R. T.J.
Correct raw material type and size?	<b>\</b>			Tag(s) to use: 76148 Tag(s) used: 76148
Setup performed according to W/O?	<b>V</b>			
Product is acceptable according to customer-specific requirements?  [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	/			[ <u>Fab:</u> Print Rev: /, W/O Rev: _ O, Part Spec Rev: _ O] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/			100
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?			1	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			/	
Required gages available & functional?	/			
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due)  MIC 01 4/24 - 7/24  CP 2 4/24 - 7/24  TP 01 1/24 - 1/25
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	/			
Required PPE being worn?	/			
Forms are the latest revision per Quality intranet?	/			List Forms (Observed Rev vs Intranet Rev)
Hardcopy Controlled Documents are isted on Quality Intranet by location?			/	List Documents and their Location: