Process/Product Audit Checklist

	1.7			(s) 14GAGALVG6036x80 Auditor DeANB
Gauge Range: 0705-086 Actual Gar	Jge:	072	\	Vidth Range: Width Actual:
Length Range: 80-80.675 Length Acti	µal: <u>گ</u>	0.06	3	Other: Other Actual:
Other: Other Actual:	1/4		Other	Other Actual.
Item	YES	NC	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	V			Cody And Clyde
Correct raw material type and size?				Tag(s) to use:
Setup performed according to W/O?	V	1		
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]		/		[Fab: Print Rev. W/O Rev: Part Spec Rev: [] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	1			
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?				
Non-conforming material put into reject warehouse and physically put into non-conforming area?				
Required gages available & functional?	V			
All Gages Calibrated (List in Comments)	V			Gages Observed (list last calibration and when due) Mic 043 1/17 - 7/17 Tape 010 1/17 - 7/17
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?				
Required PPE being worn?	V			
Forms are the latest revision per Quality ntranet?		/		List Forms (Observed Rev vs Intranet Rev)
Hardcopy Controlled Documents are isted on Quality Intranet by location?				List Documents and their Location: Lyn - F - OOI - Server