Process/Product Audit Checklist

100	4//	<i>1</i>	. wit IT(s) 35/M-26/6-1F/NOOD DEAUB.
Gauge Range -0576 0695Actual Gau				/idth Range: 60 -60.75° Width Actual: 60.067
Length Range 78.43 - 18.22 Length Actu	al: <u>78</u>	375	01	ther All Other Actual All
Other: Other Actual:	NA		Other:	Other Actual:
Item	YÉS	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to frequency and sampling required?	V			LACY-VINN
Correct raw material type and size?	V	/		Tag(s) to use: NB3847
Setup performed according to W/O?	V	,		
Product is acceptable according to customer-specific requirements? (Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?)	V			(<u>Fab:</u> Print Rev. W/O Rev. Part Spec Rev: (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?				
Visual Inspection performed and product meets requirements?		/		
Out of spec noted, with actions taken?	V			
Non-conforming material put into reject warehouse and physically put into non-conforming area?		/	1	
Required gages available & functional?				
All Gages Calibrated (List in Comments)				Gages Observed (list last calibration and when due) TAPE OI 1/17 - 7/17 M; c*039 3/17 - 8/17
Housekeeping, Machine/Floor clean? Loose tags & paperwork cleaned up?	V			
Required PPE being worn?	V			
Forms are the latest revision per Quality Intranet?	/			List Forms (Observed Rev vs Intranet Rev)
Hardcopy Controlled Documents are listed on Quality Intranet by location?	V			List Documents and their Location: Lyn-F-DDI-Sepver