Process/Product Audit Checklist

Gauge Range: -4951 Actual Gau	ge:	498	v	/idth Range: 19911-1503 Width Actual: 1500
Length Range: 24.767 - 24.553 Length Actu	al: 24	310	0	ther: 5.187 - 5.313 Other Actual: 5.740
Other:	d		Other	Other Actual:
item	YES	NO	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	X			CHICKS POLUMENTED
				Tag(s) to use: 588098
Correct raw material type and size?	×			Tag(s) used: <u>くろらつ</u> ら
Setup performed according to W/O?	X		3	
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	P			[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	B			P.S PAUT
Visual Inspection performed and product meets requirements?	X			
Out of spec noted, with actions taken?			X	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			×	
Required gages available & functional?	X			
All Gages Calibrated (List in Comments)	×			Gages Observed (list last calibration and when due) 1215 - FLB 18 DUL FLB 19 77048 - FLB 18 DUL FLB 19 7092 - FLB 18 DUL FLB 19
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	×			LOWES GOOD IN ARCY - NO LOOPE
Required PPE being worn?	X			
Forms are the latest revision per Quality Intranet?	P		- 11	List Forms (Observed Rev vs Intranet Rev)
Hardcopy Controlled Documents are listed on Quality Intranet by location?	p			List Documents and their Location: Of - Hour Of DKW, BLAKIOW TD SKID - FOUR