Process/Product Audit Checklist

PWC: 15/1 W/O#: 98496 Date:				#(s): LSV OUT Auditor: B. SWATER
Gauge Range: 1116 - 1276 Actual Ga	uge:	116	7	Width Range: <u>仏幻がらいが</u> Width Actua: <u></u> もらいの
Length Range: 156.54 - 156.00 Length Act	ual: 1	56.2	<u> </u>	Other: NA Other Actual: NA
Other: N/A Other Actual:	N	4	Othe	
Item	YES	N		(V/)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	X			
Correct raw material type and size?	×			Tag(s) to use: 63475 Tag(s) used: 73475
Setup performed according to W/O?	1/.			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	×			[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	ゃ			SILVER CANT
Visual Inspection performed and product meets requirements?	1			
Out of spec noted, with actions taken?			P	
Non-conforming material put into reject warehouse and physically put into non-conforming area?		-	P	
Required gages available & functional?	8			
All Gages Calibrated (List in Comments)	Q			OIL - FLB 19 OUL FLB 20 Gages Observed (list last calibration and when due) T1009 - MUL 18 OUL AUG 19
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	p			
Required PPE being worn?	×			
Forms are the latest revision per Quality ntranet?	×			List Forms (Observed Rev vs Intranet Rev) PAC-BB(-LTL REV Y VS PAVL)
Hardcopy Controlled Documents are isted on Quality Intranet by location?			X	List Documents and their Location: