Process/Product Audit Checklist

Gauge Range: .114 30 Actual Gau	ge:	116	V	Vidth Range: M: (\ E & Width Actual:	
Length Range: 203.0-203.5 Length Actu	al:	11.75	· 5 0	Vidth Range: M:(() ಕ್ರೋ Width Actual:	
Other: Other Actual:			Other		
ltem	YES	NO	N/A		
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	V				
Correct raw material type and size?	/			Tag(s) to use: ND 76329 Tag(s) used: ND 76329	
Setup performed according to W/O?	/				
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	/			[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)	
Packaging is acceptable according to customer-specific requirements?		V	•	Rev:] (Leave blank if non-Fab audit) JDO Cross Blocks 5,000 Max 1: Ft-Ar 6,000 M	3″,
Visual Inspection performed and product meets requirements?					to g
Out of spec noted, with actions taken?			/		
Non-conforming material put into reject warehouse and physically put into non-conforming area?			/		
Required gages available & functional?				10-1" Mic 009 4/26/22 lue 4/26/ √3305 AGT Lasor Measuring € 7/19/21 d	23 10 71
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due)	
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	V				
Required PPE being worn?	V				
Forms are the latest revision per Quality Intranet?				List Forms (Observed Rev vs Intranet Rev) DEC-BBI-CTL 6/26/17 Rev. 4	
Hardcopy Controlled Documents are listed on Quality Intranet by location?			V	List Documents and their Location:	