Process/Product Audit Checklist

Gauge Range: 130753225 Actual Gaug	e: <u>- 3</u>	05	w	idth Range: 5.917 ^{1/ده. ا} Width Actual: 5.91
Length Range: 35 足27 ゲー・031 Length Actua	l: <u>35</u>	817	Ot	her: Other Actual:
Other: Other Actual:			Other:	
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	/			
Correct raw material type and size?		/		Tag(s) to use: 26130 Tag(s) used: 26130
Setup performed according to W/O?	/			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	/	/		[Fab: Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/			
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?		/		Operator recorded OUT length dimensi Verified part was correct, operator 1
Non-conforming material put into reject warehouse and physically put into non-conforming area?				
Required gages available & functional?				52
All Gages Calibrated (List in Comments)	/			Gages Observed (list last calibration and when due) 063 Tape 4/19 de 10/19 050 mics 5/19 de 11/19 17060339 calipers 7/19 due 1/20
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?				
Required PPE being worn?	Y			
Forms are the latest revision per Quality Intranet?			/	List Forms (Observed Rev vs Intranet Rev) No Forms @ LL l