Process/Product Audit Checklist

PWC: 68L W/O#: 32869 Date: 1					
Gauge Range: <u>.177197</u> Actual Gaug	e: <u> </u>	175	W	idth Range: 46.282 -46.54 Width	Actual: 46.712
Length Range: <u>17.72 - 77.78</u> Length Actua	al: 7 5	1.75	01	her: 44 - 46 Other Actu	al: 450
Other: NA Other Actual:	NI	4	Other:	○人 Other Actual:	NA
item	YES	NO	N/A	Comments/Action Taken	(Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	p				
Correct raw material type and size?				Tag(s) to use: \$74.17_	
	Y			Tag(s) used: <u>\$9412</u>	
	120			Tag(s) used: \$9412	
Setup performed according to W/O?	×				
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	\$			[Fab: Print Rev:, W/O Rev, Leave blank if non-	
Packaging is acceptable according to customer-specific requirements?	p			GONLOS	
Visual Inspection performed and product meets requirements?	ю				
Out of spec noted, with actions taken?			×		
Non-conforming material put into reject warehouse and physically put into non-conforming area?			K		
Required gages available & functional?	P				
All Gages Calibrated (List in Comments)	p			Gages Observed (list last calibra 1205 fhb: 1B PUC 7086 JAN'LB PUC TROTT MAL'18 DE	ation and when due) FRB 119 JYW 119 X MML 119
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	Ø				
Required PPE being worn?	X				
Forms are the latest revision per Quality Intranet?	4			List Forms (Observed Rev vs Int 6ADOZO FCV (15 (9.5.15)	ranet Rev)
Hardcopy Controlled Documents are listed on Quality Intranet by location?	þ			List Documents and their Locati	on: J.D fowe office, BARAMA