Process/Product Audit Checklist

Date: 4	7.10			
Gauge Range: Actual Gaug	e:			idth Range: 48.11 - 48.00 Width Actual: 48.5
ength Range: 96.50 - 7600 Length Actua	ıl: <u>90</u>	1.25	Ot	her: SQ(50) Other Actual: (311)
Other: Other Actual:		9	Other:	Other Actual:
item	YES	NO	N/A	
Process Inspection Sheets filled out according to frequency and sampling required?	×			
Correct raw material type and size?	×			Tag(s) to use: 55370 Tag(s) used: 55370
Setup performed according to W/O?	P			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	p			[Fab: Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fáb audit)
Packaging is acceptable according to customer-specific requirements?	X			ON EXMO IN MIDALL - 6008 . 6" CLARANCE UNDER BUNGET - 600
Visual Inspection performed and product meets requirements?	4			
Out of spec noted, with actions taken?			4	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			€	
Required gages available & functional?	p			
All Gages Calibrated (List in Comments)	p			Gages Observed (list last calibration and when due) 11015 - 1.31.17 DUL 1.31.18 003 - 12.70.16 DUL 12.70.17 3124316 - 5.50.17 DUL 5.50.18
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	P			
Required PPE being worn?	Ø			
Forms are the latest revision per Quality Intranet?	×			1661 - CTL KW 4 US
Hardcopy Controlled Documents are listed on Quality Intranet by location?	p			List Documents and their Location: Q.P BULLETIN BONED 50 (KID - OP. PLATFORM, PARKAGING, WOOD)