Process/Product Audit Checklist

PWC: LPI W/0#: 21603 Date:	09/29	21	Part #(s): P113392E Auditor: N. RAGLAND
Gauge Range: 022-026 Actual Gau	ge:_ .O :	24	v	Vidth Range: 30.514-30. Width Actual: 30.53
Length Range: 64.053-64.073 ength Actu	ial: <u>64</u>	.063	o	ther: .240260 Other Actual: .250
Other: N/4 Other Actual:			Other	Other Actual:
item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	1			OPERATOR - ERIC HAVES
Correct raw material type and size?	~			Tag(s) to use: (42729 Tag(s) used: (42729
Setup performed according to W/O?	V			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	~			[Fab: Print Rev:, W/O Rev:, Part Spec Rev: (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/			
Visual Inspection performed and product meets requirements?	V			
Out of spec noted, with actions taken?			V	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			~	
Required gages available & functional?	V			
All Gages Calibrated (List in Comments)	/	5-		Gages Observed (list last calibration and when due) MIC OI OI/ZI - OI/ZZ TP OI OI/ZI - OI/ZZ LSZ CALIPERS OI/ZI - OI/ZZ
Housekeeping: Machine/Floor clean? . Loose tags & paperwork cleaned up?	V			
Required PPE being worn?	1			
Forms are the latest revision per Quality ontranet?	/			List Forms (Observed Rev vs Intranet Rev)
Hardcopy Controlled Documents are isted on Quality Intranet by location?			V	List Documents and their Location: