

Inspection Station

Description:

This station is to be used as an inspection point for finished coils that are sent through the banding line. Side number 1 is to be inspected for non-conformities while the finished coil is on the arm of the turnstile. Side number 2 is to be inspected for non-conformities while the coil is lying on the rolling table, prior to being banded.

