## **Process/Product Audit Checklist**

Cust #: 3070 Customer: HILL PHOENIX GRP/Size/GRD/Width: GVS 0.024 CB40 CD				
PWC:LLZ W/0#:18878 Date:01/25/21 Part #(s): P113364D Auditor: N. RAGLAND				
Gauge Range: 0.072-0.076 Actual Gauge: 0.022 Width Range: 30.514 - 30.534 Width Actual: 30.514				
Length Range: 60.053-60.073 Length Actual: 60.0625			ot	ole Diameter O. 240-0.260 Other Actual: 0.245
Other: NA Other Actual: Other: NA Other Actual:				
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	/		!	OPERATOR: ADAM SHACKLEFORD
Correct raw material type and size?	/			Tag(s) to use: 122275  Tag(s) used: 122275
Setup performed according to W/O?	/			
Product is acceptable according to customer-specific requirements?  [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	/			[ <u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/			
Visual Inspection performed and product meets requirements?	<b>V</b>			
Out of spec noted, with actions taken?			V	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			/	
Required gages available & functional?	/			
All Gages Calibrated (List in Comments)	<b>V</b>	0.00		Gages Observed (list last calibration and when due) LS-2 CALIPERS 01/21 DUE - 01/22 LS-3 TAPELINE 01/21 DUE - 01/22 OSO MILROMETER 01/21 DUE - 01/22
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	<b>V</b>			
Required PPE being worn?	V			
Forms are the latest revision per Quality Intranet?	V			LYN - LA - 001 REV 3
Hardcopy Controlled Documents are listed on Quality Intranet by location?				List Documents and their Location: