Process/Product Audit Checklist

Cust #: 3337 Customer:				Addit Checklist
oustollier.			GI	RP/Size/GRD/Width: POS/IF/CSOTP/60.25
PWC: 1881 W/O#: 163459 Da			Part a	#(s): 47-63707-10 Auditor: JP. 10
Gauge Range: 122/35 Actual (Gauge:	126		Width Range: 60.35-ME Width Actual: 60.75
Length Range: Length A	ctual:	2. 75		Other: 537 Mar Other Actual: 5125187
Other: Other Actual:	Nla) -	Othe	
Item	YES			Other Actual:
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	1			rate (Required for NO)
Correct raw material type and size?	/			Tag(s) to use:
Setup performed according to W/O?	/			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	/			[<u>Fab:</u> Print Rev: W/O Rev: Part Spec
Packaging is acceptable according to customer-specific requirements?	/			Rev:] (Leave blank if non-Fab audit)
Visual Inspection performed and product meets requirements?	1			Bout sheet was replaced
Out of spec noted, with actions taken?			/	The state of the s
lon-conforming material put into reject varehouse and physically put into non- onforming area?				
equired gages available & functional?	/			
l Gages Calibrated (List in Comments)			G	Tape - 73033 AUG 19 PUK AUG 20 Microne & - 012 FEB 19 DUK FAB 120
ousekeeping: Machine/Floor clean? ose tags & paperwork cleaned up?	1			Meron 6- 012-1-8 19 DUC FAB 120
quired PPE being worn?	1			
rms are the latest revision per Quality ranet?	/		Lis £	St Forms (Observed Rev vs Intranet Rev) OEC-BBI-LTL 4/20/17 Ray 4 VS EC-Pes-001 10/25/18 Res 5 VS
dcopy Controlled Documents are ed on Quality Intranet by location?	1		6	- Bulleth Bard
		11/1	3/16	D Skid - Pky + wood gress Rev.1