Process/Product Audit Checklist

0740									
Cust #: 2719 Customer: ALTEC			GRP	/Size/GRD/Width: GNS/.1084/CB40NO/60					
PWC: SCT W/O#: 75875 Date:	10/25/2	2019	Part #(s	s): <u>970510050</u> Auditor: B. CLEM					
Gauge Range: .09741174 Actual Gau	ıge:	099	W	/idth Range: 60-60.9999 Width Actual: 60.017					
Length Range: 109-109.125 Length Actu	ıal: <u>1</u>	09.125		-LATN :her:_012 Other Actual:LESS .12					
SQ Other: 031 Other Actual:	LESS	.06	Other:	N/A Other Actual: N/A					
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)					
Process Inspection Sheets filled out				Terry W.					
according to <u>frequency</u> and <u>sampling</u>	Х								
required?	<u> </u>								
				Tag(s) to use: NB63455					
Correct raw material type and size?	×			Tag(s) used: NB63455					
Setup performed according to W/O?	х								
Product is acceptable according to									
customer-specific requirements?									
[Fab: Is the Part Print Present & the	Х								
correct Revision? Are required				[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec					
measurements documented?)				Rev:] (Leave blank if non-Fab audit)					
Packaging is acceptable according to	×								
customer-specific requirements?									
Visual Inspection performed and	Х								
product meets requirements?	<u> </u>			Width .025 under. 59.975 ok'd by Patrick.					
Out of spec noted, with actions taken?	X			The investor and on our or and by Futuron.					
Non-conforming material put into reject									
warehouse and physically put into non-		Х		Width ok'd by Patrick					
conforming area?									
Required gages available & functional?	Х								
	X			Gages Observed (list last calibration and when due)					
All Gages Calibrated (List in Comments)				13-01 25' TAPE 7/11/19 7/11/20 11-03 12' TAPE 7/11/19 7/11/20 M50 1" MIC 8/13/19 8/13/20 ST-5 STEP GAUGE 7/1/19 7/1/20					
				63294 MEASURING TABLE 4/24/19 4/24/20					
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	Х								
Required PPE being worn?	Х			L'A Farrage (Observed Barrage)					
Forms are the latest revision per Quality Intranet?	x			List Forms (Observed Rev vs Intranet Rev) FOP081 2/16/01 1					
Hardcopy Controlled Documents are listed on Quality Intranet by location?	х			List Documents and their Location: SMT-CTL-001 JM-OP-001 SMT-SH-001					



Material Inspection Report

LOCATION		Sumter						DATE		10/25/2019
CUSTOMER			ALTEC			JOB # SMT	75875		Page 1	
Gauge	Order Dim]	Tolerances	Tolerances			Low Limit		High Limit	
Width		60.000	٦	0.000	-	0,00	7	0,09	⊣	0,117 60,999
Length		109.000	-	0.000	4		7	109.00	_	109.125
Course		Set up Target		Side Type	L	Skid Type Error				Skid Code 0
Gauge Width	0,107 60,500	4	IDOBORD		SOPS			٦		
Length		109.063	-{	JDOP008 JDOP014		JDOP016 JDOP034		JDOP046 JDOP032		
					_			31701.037	J	
Finished Goods Ta		95553		557		540638				
Master Coil Numb	er				L					
Heat										
Enhanced Weight							Γ		T	
Gross Weight		5100		5100		870				
Tare		140		140		140			1	
Net Weight		4960		4960		730	1	0	\vdash	0
Bundle Status					\vdash		1-		\dagger	<u> </u>
Good Pcs.		27		27	Г	4	一		╁	
Scraped Pcs.		***			┢				╁	
Rockwell				*****		***************************************	\vdash		╁	
E		0.099		0,099		0,099				
Gauge Head C	CE	0.099		0.099	├	0,099				
Body C	E	V.V./		0.072		0.077			士	
	E		_		-		\vdash	-	\vdash	
Tail	E) C									
[
Surface		ОК		ОК		OK				
Width Head		60.017		59.975	L	59.975	L		Ī	
Body		60.017		59,975	L	59,975	L			
Tail		60,017		59,975	L	59.975	L,			1
Shape		LESS.12		LESS.12		LESS.12				
Residual Check		LESS.12		LESS.12		LESS.12			T	
Length Head		109,125		109,125		109.125	T			
Body		109,125		109,125		109.125			1	
Tail		109,125	_	109,125	Γ	109.125			┢	
Squareness		LESS.06	-	LESS.06		LESS.06	Ħ		 	1
Camber										
Operator					H	-		****		-
Setup Approval	_	***************************************	_				-	· · · · · · · · · · · · · · · · · · ·	\vdash	
Run Time	s		F			Down Time	s		F	
Total Run Time	1~	0:00	_	Cost	إزاد	\$0.00	H	Cst/Hour	1	\$400.00
		, ,, - J		Limitoria .		1 40.00	LI	- Con riout		4100,00
Comments		Low width ok'd per F	atri	UK.						