Process/Product Audit Checklist

Cust #: 3072 Customer: B8020 3003 6E Trans -TX GRP/Size/GRD/Width: POS/11/CS BTP/60.0x(20)				
PWC: 881 W/O#: 83774 Date: 10/4/18 Part #(s): 88A3A 32625 Auditor: R. Rowland				
Gauge Range: . 11 2 128 Actual Gauge: . 116, . 116 Width Range: 60 - 60.25 Width Actual: 60. 75				
Length Range: 120-120.25 Length Actual: 120.125 Other: Square . 25 M Other Actual: .125				
Other: Other Actual: Other: Other Actual:				
item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	V			
Correct raw material type and size?	~			Tag(s) to use: ND 59604 Tag(s) used: ND 59604
Setup performed according to W/O?				
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]		/		[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?				
Visual Inspection performed and product meets requirements?				
Out of spec noted, with actions taken?	/			Old by audity. Part Spec to be corrected by Princes
Non-conforming material put into reject warehouse and physically put into non-conforming area?			V	
Required gages available & functional?		1		
All Gages Calibrated (List in Comments)	/		M	Gages Observed (list last calibration and when due) 35'Tape T10 32 Due Aug 2019 0-1" Mic 008 Due July 2019
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	/			
Required PPE being worn?	V			
Forms are the latest revision per Quality Intranet?	/			List Forms (Observed Rev vs Intranet Rev) DEC-BB(-CTL 6/26/17 Rev. 4
Hardcopy Controlled Documents are listed on Quality Intranet by location?	V	,		List Documents and their Location: