Process/Product Audit Checklist

FWC: R8 W/O#: 849 Date:	2/22	119		s): 47-63707-12Auditor: 5P
Gauge Range: . 093105 Actual Gau				Vidth Range: 60.25-AE Width Actual: 60.75
20.025 - 20-8/3 Length Range: Length Act	ual: /20	. 75		ther: \$ 7.37 Max Other Actual: 442 - 375
Other: VIA Other Actual:	A STATE OF THE PARTY OF THE PAR	CONTRACTOR DE NAMEDON DE		Other Actual: WA
Item	YES	NO	N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	1			
Correct raw material type and size?	/			Tag(s) to use: <u>NO 6/450</u> NO 6/449 Tag(s) used: <u>NO 6/450</u> NO 6/449
Setup performed according to W/O?	1	To Allendar		
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]				[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	/	NASA V		
Visual Inspection performed and product meets requirements?	/			
Out of spec noted, with actions taken?	1			,
Non-conforming material put into reject warehouse and physically put into non- conforming area?	1			Tas # 198259 was rejected for Pickle stails.
Required gages available & functional?				
All Gages Calibrated (List in Comments)				Microreter - 012 - GRB 19 DVK FGS 20
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	1			
Required PPE being worn?	1			
Forms are the latest revision per Quality ntranet?			l	ist Forms (Observed Rev vs Intranet Rev) OEC - BBI - CTL 4/26/17 Ray 4 15 Rev OEC - Oks - ool 10/25/18 Ray 5 15 Rev
Hardcopy Controlled Documents are isted on Quality Intranet by location?	1			ist Documents and their Location: AP - Bulletia Board JD Shid - Plant wood Areas