Process/Product Audit Checklist

Cust #: 15 Customer: HAIL	-FAC	?	GRP	Size/GRD/Width: 1465/250/5550/8.531x 546
): 112-8767-033 Auditor: 8 SW 1574
•				idth Range: 8.501 - Width Actual: 8.57
				her: <u>/ 6.44 - / 0.56</u> Other Actual: <u> </u>
Other: 44 - 46 Other Actual:			Other:	Λ
Item	YES		N/A	
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	X		ř	
Correct raw material type and size?	×			Tag(s) to use: 302/00 Tag(s) used: 302/00
Setup performed according to W/O?	ゲ			PRESS BRYKE PROGRAM 112 - 8707-038
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	大			[<u>Fab:</u> Print Rev:
Packaging is acceptable according to customer-specific requirements?	×		•	WOOD PALLET
Visual Inspection performed and product meets requirements?	ょ			
Out of spec noted, with actions taken?			X	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			×	
Required gages available & functional?	X			
All Gages Calibrated (List in Comments)	X		-	COOP EXIPER - 7.10.21 PUX 7.20.21 Gages Observed (list last calibration and when due) PO-94-15 - 1.18.22 PUL 7.18.22 POOI - 7.20.21 PUL 7.20.22
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	×			
Required PPE being worn?	X	· .		
Forms are the latest revision per Quality Intranet?	4			List Forms (Observed Rev vs Intranet Rev) TOM - F - 014 Raw O IS Raw O GADOSA RAW I US RAW I
Hardcopy Controlled Documents are listed on Quality Intranet by location?			X	List Documents and their Location:
501			11/8/1	.6