Process/Product Audit Checklist

Cust #: 2172 Customer: BSH - TN		***************************************	CDD	le: tens had a
The state of the s			GRP	/Size/GRD/Width: GVS/.0475/CB30CD/48
PWC: SRB W/O#: 81443 Date:	4/19/202	1	Part #(s	s); 9000437961 Auditor: B. Clem
Gauge Range: .04360496 Actual Gau	ge:	0475		/idth Range: <u>48-48.1875</u> Width Actual: <u>48.089</u>
Length Range: 96-96.250 Length Actu	al: <u></u> 9	6.125		vB-F her: 012 Other Actual: Less .12
SQ Other: 012 Other Actual: W	as Not C	hecked	Other:	N/A Other Actual: N/A
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?		×		Sam Jackson Operator did not do any square checks. Shape checks were done but not recorded on the inspection sheet.
Correct raw material type and size?	x			Tag(s) to use:
Setup performed according to W/O?	×			
Product is acceptable according to customer-specific requirements? [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	Х			[<u>Fab:</u> Print Rev:, W/O Rev:, Part Spec Rev:] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	Х			
Visual Inspection performed and product meets requirements?	×			
Out of spec noted, with actions taken?			N/A	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			N/A	
Required gages available & functional?	×			
All Gages Calibrated (List in Comments)	х			Gages Observed (list last calibration and when due) 8-3 25' Tape 10/13/2020 10/13/2021 M50 1" Mic 1/8/2021 1/8/2022 ST-5 Step Gauge 6/23/2020 6/23/2021 63294 Measuring Table 5/1/2020 5/1/2021
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	×			
Required PPE being worn?	Х			
Forms are the latest revision per Quality Intranet?	х			List Forms (Observed Rev vs Intranet Rev) FOP081 2/18/01 REV 1
Hardcopy Controlled Documents are listed on Quality Intranet by location?	х			List Documents and their Location: SMT-SRB-001 JM-OP-001



Material Inspection Report

LOCATION CUSTOMER		Sumter			DATE	4/19/2021
		BSH	TNN	JOB # SMT	81443	Page 1
		Order Dim	Tolerances	Tolerances	Low Limit	High Limit
Gauge		0.046		+ 0.004	0.044	0.050
Width		48.000	- 0.000	+ 0.188	48.000	48.188
Length		96.000	0.000	+ 0.250	96.000	96.250
		Set up Target	Side Type	3 Skid Type Error		Skid Code 3 2
Gauge		0,047		SOP'S		
Width		48.094	JDOP008	JDOP016	JDOP046	
Length		96.125	JDOP014	JDOP034	JDOP032	
Finished Goods Tag		BT43834	143837			
Master Coil Num	ber	553105				
Heat						
Enhanced Weight						
Gross Weight		4730	4730			
Tare		90	90			
Net Weight		4640	4640	0	0	0
Bundle Status	1000					
Good Pcs.		75	75			
Scraped Pcs.		<u> </u>		12 / San 14 Maria - 11 / 10	6.3.	
Rockwell			10.			
E		0.047	0.047			
Gauge Head C	C	0.048	0.048			
Body E		0.047	0.047		E. 100 (E	
	C					
	E					
Tail	C			7		
Surface	I E					
Width Head		48.089	48.100			
Body						
Tail						
Shape	17.74	44.	4			
Residual Check						
Length Head		96.125	96.125			
Body						
Tail						
Squareness		Paris San Paris	4 May 2 (2017)			
Camber						
Operator						
Setup Approval						
Run Time	S		F	Down Time	S	F
Total Run Time		0:00	Cost	\$0.00	Cst/Hour	\$400.00
. com rom rimo		3,30	1 7 5 3 5	1		
Comments	1.39					