## **Process/Product Audit Checklist**

Cust #: 10 Customer: Hull			_ GRP/Size/GRD/Width: HKS/150/5550/17000
			Part #(s): 272-9604-001 Auditor: 6.5 14.1781
			Width Range: 12.01 - 11.94 Width Actual: 11.98
			Other: MA Other Actual: MA
Other: 11 Other Actual:			Other: NA Other Actual: NA
ltem	YES		N/A Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	X		64009 BKING URLIAND
Correct raw material type and size?		と	Tag(s) to use: 207236  Tag(s) used: TMG NOT AVMIKE  O P.S.
Setup performed according to W/O?	N		
Product is acceptable according to customer-specific requirements?  [Fab: Is the Part Print Present & the correct Revision? Are required measurements documented?]	×		[ <u>Fab:</u> Print Rev: W/O Rev: Part Spec Rev: ] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	p		WOOD PALLET
Visual Inspection performed and product meets requirements?	p		
Out of spec noted, with actions taken?	×		(3) SLOUP PMTS
Non-conforming materia put into reject warehouse and physical y put into non- conforming area?	X		
Required gages available & functional?	X		
All Gages Calibrated (List in Comments)	8		16105737 - OCT 2018 OUR OUT 2019 Gages Observed (list last calibration and when due) PO-94-15 - JUDIC JAW 19 OUR JUNE 19 POOM - OCT 2018 PUR OCT 2019
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?		X	DRAVITA TABLE HAR LOOSE PARCE TATOS -> CLAMED BY DESERTED
Required PPE being worr?	Ø		
Forms are the latest revision per Quality ntranet?	X		List Forms (Observed Rev vs Intranet Rev) 6000 Fau 1 15 fav 1
Hardcopy Controlled Documents are isted on Quality Intranet by location?	X		List Documents and their Location:  R.P. PLARMA, BRELLEVOW, FLOWT  OFFICE