

Process/Product Audit Checklist

Cust #: 9060 Customer: Tool & Die GRP/Size/GRD/Width: CRC/12L/CSB/48				
PWC: CR2 W/O#: 73296 Date: 9/20/2019 Part #(s): 12GAX48X87CRS Auditor: Jack Cochran				
Gauge Range: .0986-.1106 Actual Gauge: .103 Width Range: 48-48.187 Width Actual: 48.125				
Length Range: 87-87.25 Length Actual: 87.062 Flatn Other: 0-.125 Other Actual: <.125				
Other: N/A Other Actual: N/A Other: N/A Other Actual: N/A				
Item	YES	NO	N/A	Comments/Action Taken (Required for NO)
Process Inspection Sheets filled out according to <u>frequency</u> and <u>sampling</u> required?	x			John M. Michael C.
Correct raw material type and size?	x			Tag(s) to use: 19274 Tag(s) used: 19274
Setup performed according to W/O?	x			
Product is acceptable according to customer-specific requirements? [Fab : Is the Part Print Present & the correct Revision? Are required measurements documented?]	x			[Fab : Print Rev:____, W/O Rev:____, Part Spec Rev:____] (Leave blank if non-Fab audit)
Packaging is acceptable according to customer-specific requirements?	x			
Visual Inspection performed and product meets requirements?	x			
Out of spec noted, with actions taken?			x	
Non-conforming material put into reject warehouse and physically put into non-conforming area?			x	
Required gages available & functional?	x			
All Gages Calibrated (List in Comments)	x			Gages Observed (list last calibration and when due) Gauge Block 980157 11/2017 11/2020
Housekeeping: Machine/Floor clean? Loose tags & paperwork cleaned up?	x			
Required PPE being worn?	x			
Forms are the latest revision per Quality Intranet?	x			List Forms (Observed Rev vs Intranet Rev) JDM13 3/1/2017 7
Hardcopy Controlled Documents are listed on Quality Intranet by location?	x			List Documents and their Location: CLV-RB-002 JM-OP-001